

Wear It Right

3M™ Respirators



3M™ 1860/1860S Health Care N95 Particulate Respirator and Surgical Mask

APPLICATION:



1 Cup the respirator in your hand with the nosepiece at fingertips, allowing the head straps to hang freely below hand.



2 Position the respirator under your chin with the nosepiece up.



3 While holding the respirator in place, pull the top strap over your head so it rests high on the back of your head.



4 While continuing to hold the respirator firmly in place, pull the bottom strap over your head and position it around your neck, below your ears. Untwist the straps. Position the respirator low on your nose.



5 Using both hands, mold the nosepiece to the shape of your nose by pushing inward while moving your fingertips down both sides of the nosepiece. **Note: Always use two hands when molding nosepiece. Pinching with one hand may result in improper fit and less effective respirator performance.**

POSITIVE PRESSURE FIT CHECK



6 The respirator must be checked before each use. To perform the fit check, place both hands completely over the respirator, being careful not to disturb the position, and exhale sharply. If air leaks around your nose, adjust the nosepiece as described in step 5. If air leaks at respirator edges, adjust the straps back along the sides of your head. Perform fit check again if an adjustment is made. If you cannot achieve a proper fit, see your supervisor. Do not enter area requiring respirator use.

REMOVAL:



1 Without touching the respirator, slowly lift the bottom strap from around your neck up and over your head.



2 Lift off the top strap. Do not touch the respirator.



3 Store or discard according to your facility's infection control policy.

WARNING

This respirator helps protect against certain particulate contaminants, but does not eliminate exposure to or risk of contracting disease or infection. Misuse may result in sickness or death. For proper use, see your supervisor or call 3M Occupational Health and Environmental Safety Division Technical Services at 1-800-243-4630.

3M Health Care

3M Center, Building 275-4W-02
St. Paul, MN 55144-1000
U.S.A.
1 800 228-3957

www.3m.com/healthcare

3M Canada

Post Office Box 5757
London, Ontario N6A4T1
Canada
1 800-563-2921

Outside of USA, please contact your 3M Representative

Please Recycle

Printed in U.S.A.
© 3M 2006
All Rights Reserved.
70-2009-0557-1

